Plex 11/9/21 11:15 AM Dart.gagnon.michelle



Dart Aerospace Ltd. 1270 Aberdeen St Hawkesbury, ON K6A 1K7 Canada

## **ENGINEERING CHANGE REQUEST**

Tel (613) 632-5200 Fax 613 632-5246

**ECR 314** 11/9/21 9:19 AM Requested By: Date Opened: Drouin, Steven Type: Tooling/DSK/GSE Drawing Change Responsible Engineer: Tailor, Ketan Requester\*: Priority: Medium Drouin, Steven Status: **Quality Disposition** DE Approver\*: Provencal, Chris Reason: ECR Lead\*: Drouin, Steven Expense: 0 **ECR Specialist:** Drouin, Steven Target Date: **Execution Date: ECR Approval No:** RE (R&D): \*\*BRIEF DT 10745 **DESCRIPTION\*\*:** Status Note: **DESCRIPTION/ ADR** The DT10745 The following parts are under review for testing purpose. \*\*\*All part should be CONTENT\*\*: on hold and not Manufactured\*\*\* Remove W/O and Parts from Floor DT10745-041 DT10745-051 DT10745-055 DT10745-057 DT10745-059 DT10745-061 DT10745-063 DT10745-065 DT10745-067 DT10745-9 DT10745-27 DT10745-7 DT10745-9 DT10745-11 DT10745-1 DT10745-3 DT10745-5 DT10745-7 DT10745-21 DT10745-13 DT10745-17 DT10745-19 DT10745-15 **CUSTOMER APPROVALS Customer Approval Required** Customer **Customer Visible Customer Approved PARTS** 

Part No	Rev	Part Status	Name	Туре	Customer Part	Special Comments	Documents
DT10745- 041		On hold	Kit, Valve Pull Test	Finished Good	DT10745-041		
DT10745- 051		On hold	Valve Test Fixture Assembly	Sub- assembly			
DT10745- 053		On hold	Load Cell Assembly	Sub- assembly			
DT10745- 055		On hold	Adapter, Bayonet Housing	Sub- assembly			
DT10745- 057		On hold	Reservoir Adapter Assembly	Sub- assembly			
DT10745- 059		On hold	Packaging Assembly	Sub- assembly			
DT10745- 061		On hold	Plate Assembly	Sub- assembly			
DT10745- 063		On hold	Plate Assembly	Sub- assembly			
DT10745- 065		On hold	Adapter, Bayonet Housing	Sub- assembly			
DT10745- 067		On hold	Adapter, Bayonet Housing	Sub- assembly			
DT10745-1		On hold	Base	Sub- assembly			
DT10745-11		On hold	Load Cell Adapter	Sub- assembly			
DT10745-13		On hold	Load Cell Pull Cable	Sub- assembly			
DT10745-15		On hold	Adapter, Reservoir	Sub- assembly			
DT10745-17		On hold	Bracket	Sub- assembly			
DT10745-19		On hold	Guard	Sub- assembly			DT10745
DT10745-21		On hold	Cover	Sub- assembly			DT10745
DT10745-23		On hold	Foam, Bottom	Sub- assembly			
DT10745-25		On hold	Foam, Top	Sub- assembly			
DT10745-27		On hold	Link	Sub- assembly			
DT10745-29		On hold	Plate	Sub- assembly			
DT10745-3		On hold	Support	Sub- assembly			
DT10745-31		On hold	Plate	Sub- assembly			
DT10745-33		On hold	Bayonet Housing Adapter	Sub- assembly			
DT10745-35		On hold	Bayonet Housing Adapter	Sub- assembly			
DT10745-5		On hold	Support	Sub- assembly			
DT10745-7		On hold	Load Cell Support	Sub- assembly			
DT10745-9		On hold	Shroud, Test	Sub- assembly			
				INVENTO	RY DISPOSIT	ION	

Part No Revision	Material No	Current Inventory Qty	Purchasing On-Order Qty	Qty Scheduled for Production		
DT10745-041		0	0	1		
DT10745-051		1	0	1		
DT10745-053		0	0	1		
DT10745-055		0	0	1		
DT10745-057		1	0	0		
DT10745-059		0	0	0		
DT10745-061		0	0	1		
DT10745-063		0	0	1		
DT10745-065		0	0	1		
DT10745-067		0	0	1		
DT10745-1		0	0	0		
DT10745-11		0	0	1		
DT10745-13		0	0	1		
DT10745-15		0	0	0		
DT10745-17		0	0	1		
DT10745-19		1	0	1		
DT10745-21		0	0	0		
DT10745-23		0	1	0		
DT10745-25		0	1	0		
DT10745-27		0	0	1		
DT10745-29		0	0	1		
DT10745-3		0	0	0		
DT10745-31		0	0	1		
DT10745-33		0	0	1		
DT10745-35		0	0	1		
DT10745-5		0	0	0		
DT10745-7		0	0	0		
DT10745-9		0	0	1		
	·	EFF	ECTS			
	Effect Gr	roup		Effects		
	1. Quaran	tine?	Immediat	Immediate quarantine required		
2. ECR Le	ad Assessment - I	mpacted Docs & Output	Drawin	Drawing Change Required		
3. ECR	Lead Assessment	- Status During ECR	UR - I	UR - Full Under Review		
	<ol><li>Production</li></ol>	n Type	In-house production	In-house production, Outsourced/Purchased Part		